

Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942



Photo 1: Location



Photo 2: Wellhead



Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 3: Incorrect sign at pump jack

Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 4: Stained soil at engine. Some removed.

Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 5: Emergency number did not go to operator.

Inspection Photos
Location Name: Hoozee-Bjolin #1
Location ID: 318942



Photo from prior inspection for comparison



Photo 6: Oil slick on water in pit