

Inspection Photos

Location Name: Wiedeman - 65N67W / 21NESE

Location #: 306731



Photo #1

Wiedeman 43-21U (API 05-123-25168) wellhead

Erosion hole near well.



Photo #2

Wiedeman 33-21U, 43-21U Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources