

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2018

Submitted Date:

05/20/2018

Document Number:

674104411**FIELD INSPECTION FORM**

Loc ID 449874	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 7 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																																											
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>cogccnotifications@laramie-energy.com</td> <td>All inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment			cogccnotifications@laramie-energy.com	All inspections																																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																																								
		cogccnotifications@laramie-energy.com	All inspections																																																																																																																																								
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>449831</td><td>WELL</td><td>PR</td><td>01/15/2018</td><td>OW</td><td>077-10365</td><td>Bruton 19-12E</td><td>RI</td></tr> <tr><td>449833</td><td>WELL</td><td>PR</td><td>12/30/2017</td><td>OW</td><td>077-10366</td><td>Bruton 19-13E</td><td>RI</td></tr> <tr><td>449834</td><td>WELL</td><td>PR</td><td>12/30/2017</td><td>OW</td><td>077-10367</td><td>Bruton 19-17E</td><td>RI</td></tr> <tr><td>449840</td><td>WELL</td><td>PR</td><td>11/19/2017</td><td>OW</td><td>077-10368</td><td>Bruton 19-19E</td><td>RI</td></tr> <tr><td>449843</td><td>WELL</td><td>PR</td><td>12/30/2017</td><td>OW</td><td>077-10369</td><td>Bruton 19-18E</td><td>RI</td></tr> <tr><td>449846</td><td>WELL</td><td>PR</td><td>11/10/2017</td><td>OW</td><td>077-10370</td><td>Bruton 30-02E</td><td>RI</td></tr> <tr><td>449847</td><td>WELL</td><td>PR</td><td>11/15/2017</td><td>OW</td><td>077-10371</td><td>Bruton 30-01E</td><td>RI</td></tr> <tr><td>449848</td><td>WELL</td><td>PR</td><td>11/19/2017</td><td>OW</td><td>077-10372</td><td>Bruton 19-21E</td><td>RI</td></tr> <tr><td>449849</td><td>WELL</td><td>PR</td><td>12/24/2017</td><td>OW</td><td>077-10373</td><td>Bruton 19-21W</td><td>RI</td></tr> <tr><td>449850</td><td>WELL</td><td>PR</td><td>11/22/2017</td><td>OW</td><td>077-10374</td><td>Bruton 19-19W</td><td>RI</td></tr> <tr><td>449851</td><td>WELL</td><td>PR</td><td>11/20/2017</td><td>OW</td><td>077-10375</td><td>Bruton 19-20W</td><td>RI</td></tr> <tr><td>449852</td><td>WELL</td><td>PR</td><td>11/01/2017</td><td>OW</td><td>077-10376</td><td>Bruton 19-18W</td><td>RI</td></tr> <tr><td>449853</td><td>WELL</td><td>PR</td><td>12/29/2017</td><td>OW</td><td>077-10377</td><td>Bruton 19-14E</td><td>RI</td></tr> <tr><td>449854</td><td>WELL</td><td>PR</td><td>11/09/2017</td><td>OW</td><td>077-10378</td><td>Bruton 19-20E</td><td>RI</td></tr> <tr><td>449855</td><td>WELL</td><td>PR</td><td>12/24/2017</td><td>OW</td><td>077-10379</td><td>Bruton 19-17W</td><td>RI</td></tr> <tr><td>449875</td><td>WELL</td><td>PR</td><td>12/28/2017</td><td>OW</td><td>077-10380</td><td>Bruton 19-16E</td><td>RI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	449831	WELL	PR	01/15/2018	OW	077-10365	Bruton 19-12E	RI	449833	WELL	PR	12/30/2017	OW	077-10366	Bruton 19-13E	RI	449834	WELL	PR	12/30/2017	OW	077-10367	Bruton 19-17E	RI	449840	WELL	PR	11/19/2017	OW	077-10368	Bruton 19-19E	RI	449843	WELL	PR	12/30/2017	OW	077-10369	Bruton 19-18E	RI	449846	WELL	PR	11/10/2017	OW	077-10370	Bruton 30-02E	RI	449847	WELL	PR	11/15/2017	OW	077-10371	Bruton 30-01E	RI	449848	WELL	PR	11/19/2017	OW	077-10372	Bruton 19-21E	RI	449849	WELL	PR	12/24/2017	OW	077-10373	Bruton 19-21W	RI	449850	WELL	PR	11/22/2017	OW	077-10374	Bruton 19-19W	RI	449851	WELL	PR	11/20/2017	OW	077-10375	Bruton 19-20W	RI	449852	WELL	PR	11/01/2017	OW	077-10376	Bruton 19-18W	RI	449853	WELL	PR	12/29/2017	OW	077-10377	Bruton 19-14E	RI	449854	WELL	PR	11/09/2017	OW	077-10378	Bruton 19-20E	RI	449855	WELL	PR	12/24/2017	OW	077-10379	Bruton 19-17W	RI	449875	WELL	PR	12/28/2017	OW	077-10380	Bruton 19-16E	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																				
449831	WELL	PR	01/15/2018	OW	077-10365	Bruton 19-12E	RI																																																																																																																																				
449833	WELL	PR	12/30/2017	OW	077-10366	Bruton 19-13E	RI																																																																																																																																				
449834	WELL	PR	12/30/2017	OW	077-10367	Bruton 19-17E	RI																																																																																																																																				
449840	WELL	PR	11/19/2017	OW	077-10368	Bruton 19-19E	RI																																																																																																																																				
449843	WELL	PR	12/30/2017	OW	077-10369	Bruton 19-18E	RI																																																																																																																																				
449846	WELL	PR	11/10/2017	OW	077-10370	Bruton 30-02E	RI																																																																																																																																				
449847	WELL	PR	11/15/2017	OW	077-10371	Bruton 30-01E	RI																																																																																																																																				
449848	WELL	PR	11/19/2017	OW	077-10372	Bruton 19-21E	RI																																																																																																																																				
449849	WELL	PR	12/24/2017	OW	077-10373	Bruton 19-21W	RI																																																																																																																																				
449850	WELL	PR	11/22/2017	OW	077-10374	Bruton 19-19W	RI																																																																																																																																				
449851	WELL	PR	11/20/2017	OW	077-10375	Bruton 19-20W	RI																																																																																																																																				
449852	WELL	PR	11/01/2017	OW	077-10376	Bruton 19-18W	RI																																																																																																																																				
449853	WELL	PR	12/29/2017	OW	077-10377	Bruton 19-14E	RI																																																																																																																																				
449854	WELL	PR	11/09/2017	OW	077-10378	Bruton 19-20E	RI																																																																																																																																				
449855	WELL	PR	12/24/2017	OW	077-10379	Bruton 19-17W	RI																																																																																																																																				
449875	WELL	PR	12/28/2017	OW	077-10380	Bruton 19-16E	RI																																																																																																																																				

Contact Name	Phone	Email	Comment
		cogccnotifications@laramie-energy.com	All inspections

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449831	WELL	PR	01/15/2018	OW	077-10365	Bruton 19-12E	RI
449833	WELL	PR	12/30/2017	OW	077-10366	Bruton 19-13E	RI
449834	WELL	PR	12/30/2017	OW	077-10367	Bruton 19-17E	RI
449840	WELL	PR	11/19/2017	OW	077-10368	Bruton 19-19E	RI
449843	WELL	PR	12/30/2017	OW	077-10369	Bruton 19-18E	RI
449846	WELL	PR	11/10/2017	OW	077-10370	Bruton 30-02E	RI
449847	WELL	PR	11/15/2017	OW	077-10371	Bruton 30-01E	RI
449848	WELL	PR	11/19/2017	OW	077-10372	Bruton 19-21E	RI
449849	WELL	PR	12/24/2017	OW	077-10373	Bruton 19-21W	RI
449850	WELL	PR	11/22/2017	OW	077-10374	Bruton 19-19W	RI
449851	WELL	PR	11/20/2017	OW	077-10375	Bruton 19-20W	RI
449852	WELL	PR	11/01/2017	OW	077-10376	Bruton 19-18W	RI
449853	WELL	PR	12/29/2017	OW	077-10377	Bruton 19-14E	RI
449854	WELL	PR	11/09/2017	OW	077-10378	Bruton 19-20E	RI
449855	WELL	PR	12/24/2017	OW	077-10379	Bruton 19-17W	RI
449875	WELL	PR	12/28/2017	OW	077-10380	Bruton 19-16E	RI

<b>General Comment:</b> <p>This is an Interim Reclamation &amp; Stormwater focused Inspection, a Follow Up to Insp Doc#680102913 Dated 4/18/18. Any Corrective Actions from previous Inspections that have not been addressed are still applicable. Location was Built and Wells Drilled in 2017.</p> <p>It appears that as the last Well began Production in December 2017; that Interim Reclamation should occur in June 2018 (unless subsequent drilling operations are to be commenced within 12 months).</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Inspected Facilities				
Facility ID: <u>449831</u>	Type: <u>WELL</u>	API Number: <u>077-10365</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449833</u>	Type: <u>WELL</u>	API Number: <u>077-10366</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449834</u>	Type: <u>WELL</u>	API Number: <u>077-10367</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449840</u>	Type: <u>WELL</u>	API Number: <u>077-10368</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449843</u>	Type: <u>WELL</u>	API Number: <u>077-10369</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449846</u>	Type: <u>WELL</u>	API Number: <u>077-10370</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449847</u>	Type: <u>WELL</u>	API Number: <u>077-10371</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449848</u>	Type: <u>WELL</u>	API Number: <u>077-10372</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449849</u>	Type: <u>WELL</u>	API Number: <u>077-10373</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449850</u>	Type: <u>WELL</u>	API Number: <u>077-10374</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449851</u>	Type: <u>WELL</u>	API Number: <u>077-10375</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449852</u>	Type: <u>WELL</u>	API Number: <u>077-10376</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449853</u>	Type: <u>WELL</u>	API Number: <u>077-10377</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449854</u>	Type: <u>WELL</u>	API Number: <u>077-10378</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449855</u>	Type: <u>WELL</u>	API Number: <u>077-10379</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>449875</u>	Type: <u>WELL</u>	API Number: <u>077-10380</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: [Interim Reclamation has not yet commenced at site.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

[CA from previous inspection has been resolved. Cuttings have been pulled back from top of Cut slope where they were mixing with Top soil.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

[CA from previous inspection has been resolved. Silt fence has been installed along base of Topsoil berm at base of fill slope.](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					SE corner of Cut Slope, Rill erosion
Berms	Pass	Compaction	Pass			
Sediment Traps	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass			
Waddles	Pass	Waddles	Pass			

Comment: Stormwater rill erosion is still occurring on SE section of cut slope & sediment is migrating onto Location. it appears some attempt has been made to stabilize slope, but further work is needed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/18/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401646676	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468604</a>
674104411	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475951</a>
674104412	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468602">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468602</a>