

Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

YE7

Date: 4/23/2018



Photo 1. View of former pit area located north of well pad from northern portion facing southward. Revegetation is largely comprised of crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 2. View of discolored soil indicating area of Cool-Ox[®] as indicated by Mike Hannigan. Approx. 15 of these observed.



Photo 3. View of small piece of black plastic in former pit area. Several of these observed.



Photo 4. View of Russian knapweed (*Acroptilon repens*) infestation along the northern edge of the former pit area. Approximately 2000 individuals observed. Weed control technician was onsite and actively spraying during the inspection.