

Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

YF3

Date: 4/23/2018



Photo 1. View of former pit area located south of well pad from southeastern portion facing toward the center of the well pad. Former pit area is within a cultivated field that is not in production at this time. Vegetation will need to be assessed when the field is planted and crop is established.



Photo 2. View of former pit area from the southeastern edge of the project area facing westward.