

# *Inspection Photos*

*Loc# 335982*

*Operator: Caerus*

*Inspection Number: 674104424*

*Inspection Date: 5/17/2018*





**Photo#1:**

Overview of Location from entry to North. Arrow indicates what is identified in Operator photos as spoil pile.

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335982



Photo#2:  
Looking East along base of Spoil Pile at North end of Location.

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335982



Photo#3:  
Other material piles are stored at Southwest corner of site.

May 17, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc# 335982



Photo#4:

Photo#5:

Views to base of fill slopes at West side of Location

May 17, 2018



Photo#6:  
2017 Aerial view of Location; COGCC maps.

May 17, 2018