

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2018

Submitted Date:

05/29/2018

Document Number:

679700931**FIELD INSPECTION FORM**Loc ID 327707 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	

General Comment:

Inspection by COGCC Environmental Staff. The Carlson 22-1 tank battery was impacted by the release of drilling fluids from the adjacent Krier 4 Land Application Site operated by Highpoint Operating. Highpoint Operating is responsible for the removal of drilling fluids from the tank battery location.