

Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

GP16

Date: 4/23/2018



Photo 1. View of former pit area from the eastern portion facing toward the center of the well pad. Former pit area is north of the well pad. Revegetation is largely comprised of crested wheatgrass (*Agropyron cristatum*) and smooth brome (*Bromus inermis*).



Photo 2. View of former pit area from eastern portion facing westward.



Photo 3. View of gypsum-treated area within the former pit area. Per Mike Hannigan, this area is scheduled for seeding.