

# Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

GP13

Date: 4/23/2018



**Photo 1. View of former pit area from the northern edge of the well pad facing northward. Former pit area is within a cultivated field that is not in production at this time. Vegetation will need to be assessed when the field is planted and crop is established.**



**Photo 2. View of former pit area from northern edge of well pad facing westward.**