

**UNOCAL GM 14-35**  
**Api# 05-045-07092Inspection**  
**Inspection # 689701398**



**Wells**

**UNOCAL GM 14-35**  
**Api# 05-045-07092 Inspection**  
**Inspection # 689701398**



**Separators.**



**UNOCAL GM 14-35**  
**Api# 05-045-07092 Inspection**  
**Inspection # 689701398**



**Erosion of roadside of road across from the separators.**



**UNOCAL GM 14-35**  
**Api# 05-045-07092 Inspection**  
**Inspection # 689701398**



**Sediment build up in ditch behind separators.**