

Inspection Photos
Location Name: GP-13
API: 05-083-06645
REM #9666



GP-13 location sign.



Former drilling pit area.

Inspection Photos
Location Name: GP-13
API: 05-083-06645
REM #9666



Alternate view of former drilling pit area.



GP-13 former drilling pit area.