

**Inspection Photo
Graham 32-12D (L32)
API # 045-09029
Inspection # 689301216**



Location Photo #1



Location Photo #2



**Inspection Photo
Graham 32-12D (L32)
API # 045-09029
Inspection # 689301216**



Location Photo #3, holes in containment liner



Location Photo #4 holes in containment liner

Inspection Photo
Graham 32-12D (L32)
API # 045-09029
Inspection # 689301216



Location Photo #5 holes in containment liner