

**Inspection Photo
Couey 29-13 (D32)
API # 045-08149
Inspection # 689301224**



Location Photo #1



**Location Photo #2, Stained rock inside tank
containment**

**Inspection Photo
Couey 29-13 (D32)
API # 045-08149
Inspection # 689301224**



Location Photo #3, Stained rock inside tank containment



Location Photo #4, Stained rock inside tank containment

**Inspection Photo
Couey 29-13 (D32)
API # 045-08149
Inspection # 689301224**



**Location Photo #5, Stained rock inside tank
containment**