

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2018

Submitted Date:

05/30/2018

Document Number:

691300225

**FIELD INSPECTION FORM**

Loc ID 332724 Inspector Name: Kraich, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245629	WELL	PR	01/09/2009	GW	123-13424	MENONI B30-15	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type TANK BATTERY

Comment: 4 strand wire

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Horizontal Separator

# 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Emission Control Device

# 2

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">SHares berms with produced water vaults</a>					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLs	CONCRETE SUMP/VAULT		,	
Comment:						
Corrective Action:				Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	53 BBL	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Shares berms with production tanks.</a>					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 245629 Type: WELL API Number: 123-13424 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 9/2016.  
Well is on Noble decommissioned facility list.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300226	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477650</a>