

Inspection Photos
Location Name: GP-11
API: 05-083-06635
REM #9671



Former drilling pit area on eastern edge of GP-11 location.



Eastern edge of GP-11 location where drilling pits were located.

Inspection Photos
Location Name: GP-11
API: 05-083-06635
REM #9671



Drilling pit area treated with gypsum in the fall of 2017.



Soil amendments added in the fall of 2017.