

Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

GP9

Date: 4/23/2018



Photo 1. View of former pit area from the northwestern portion facing southeastward. Former pit area is east of the well pad. Area appears seeded, little germination observed.



Photo 2. View of the northern portion of the former pit area from the northwestern corner facing eastward.



Photo 3. View of the western portion of the former pit area from the northwestern corner facing southward.