

Inspection Photos
Location Name: Gp-15
API: 05-083-06641
REM #9885



GP-15 location sign.



Area where drilling pits were located on eastern edge of GP-15 location.

Inspection Photos
Location Name: Gp-15
API: 05-083-06641
REM #9885



Area where drilling pits were located.



Eastern edge of GP-15 location.