

# Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

GP12

Date: 4/23/2018



**Photo 1. View of former pit area facing westward (north of well pad). Vegetation is grazed. Cattle exclusion may be needed to revegetate. Vegetation is needed to assess potential salt impacts.**





**Photo 2. View of the former pit area from the northeastern edge facing southwestward.**





**Photo 3. View of grazed vegetation within the interim reclamation area.**