



00234820

LEASE INSPECTION FORMDate 7/5/85Operator ~~AAA~~ R. M. P.Field WATTENBURGLease Name & No. AMOLO-STAGE 43-16County ADAMS

Tank Battery No. _____

Location 16-13-65W
Legal DescriptionType of Inspection well site

Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of TankSKIM TANK WORKOVER RIG ON LOCATIONPit No. 1 4-400 BBL FRAC TANKSPit No. 2 PITS HAVE ALL BEEN FILLED

Pit No. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

_____RECOMMENDED ACTION (If Required) GIVE SAME TIME (3MO) BEFORE
REQUESTING RM'S, PLACE IN WELL FILEINSPECTOR JJK