

Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

GP15

Date: 4/23/2018



Photo 1. View of former pit area from the northeastern portion of the project area facing southward. Former pit area is within a cultivated field that is not in production at this time. Vegetation will need to be assessed when the field is planted and crop is established.





Photo 2. View of former pit area from northern edge of well pad facing eastward.