

Inspection Photos
Location Name: Wolf Mountain 15-2-7-87
API: 05-107-06222



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Wolf Mountain 15-2-7-87
API: 05-107-06222



Photo 2. Not all tanks contain complete labels.



Photo 3. Stained gravel at wellhead and on wood. Container with fluid in it from wellhead.

Inspection Photos
Location Name: Wolf Mountain 15-2-7-87
API: 05-107-06222



Photo 4. Close-up of fluid at/from wellhead.



Photo 5. Close-up of stained gravel and riser.

Inspection Photos
Location Name: Wolf Mountain 15-2-7-87
API: 05-107-06222



Photo 6. Lube oil on pumpjack base without secondary containment.



Photo 7. Containment box at wellhead, staining from motor.