

Final Reclamation Inspection

May 31, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-20300

Inspection Document #: 682403639

Weld County, CO

SWNE Section 27 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-FOSTER RIDGE #2-27
API: 05-123-20300



Photo 1. Photo taken from the well location, facing Northwest. Wells have been plugged and abandoned. Operator shall conduct final reclamation activities per Rule 1004 by 1/12/2019.



Inspection Photos
Location Name: HSR-FOSTER RIDGE #2-27
API: 05-123-20300



Photo 2. Photo taken from the well location, facing East. Access road remains.
See comments under Photo 1.