

Inspection Photos
Location Name: McCallum Unit 97
API: 05-057-06162



Photo 1. Overview of location taken at entrance facing south.



Photo 2. No current operator or emergency number on location.