

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	May 18, 2018 10:28:19 AM MDT
Server Receive Date:	May 18, 2018 10:29:16 AM MDT
Reference Number:	20180518-1878899292
Location:	2256 Co Rd 234, Durango, CO 81301, USA May 18, 2018 10:28:07 AM MDT [View Map]

Information

Name	reclamationtablet
Date	May 18, 2018
Well Name	STATE 01-31 1 CHASTAIN GAS UNIT
API Number	50670657100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

install a couple of t posts and painted yellow picked up some debris and trash around wellsite