

Inspection Photos

API#081-06927

Operator: Western Gas Resources

Inspection Number: 674104451

Inspection Date: 5/25/2018





Photo#1:
Overview of Location to Northeast. Arrow indicates PA Marker ; in foreground is what appears to be Well head noted on site.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Iversen API#081-06927



Photo#2:

Overview of Location to Southwest. Arrow indicates what appears to be Well head noted on site. PA Marker is in foreground.

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Iversen API#081-06927



Photo#3:
Views along un-reclaimed Access road.



Photo#4:

May 25, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Western Gas Resources PA Iversen API#081-06927



Photo#5:
View along un-reclaimed Access road.

*

May 25, 2018



Photo#6:
Pipeline Riser (?) in area where Access
Road meets main road.