

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	May 31, 2018 3:44:14 PM MDT
Server Receive Date:	May 31, 2018 3:44:22 PM MDT
Reference Number:	20180531-1879872976
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA May 31, 2018 3:44:01 PM MDT [View Map]

Information

Name	reclamationtablet
Date	May 31, 2018
Well Name	LECHNER, OPAL GAS UNIT A 2
API Number	50670887400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

