



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	May 31, 2018 3:47:06 PM MDT
Server Receive Date:	May 31, 2018 3:47:11 PM MDT
Reference Number:	20180531-1879876031
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA May 31, 2018 3:46:15 PM MDT [View Map]

Information

Name	reclamationtablet
Date	May 31, 2018
Well Name	FLORIDA RIVER FACILITY
API Number	NA
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris

Picture North to South



Picture South to North



Picture East to West

