



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	May 31, 2018 3:48:45 PM MDT
Server Receive Date:	May 31, 2018 3:48:50 PM MDT
Reference Number:	20180531-1879876062
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA May 31, 2018 3:47:49 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	reclamationtablet
Date	May 31, 2018
Well Name	GARDNER J B A 1
API Number	50670758700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean up Operator Debris Clean Up Weed Debris Replaced/Repaired Well Sign

Picture North to South



Picture South to North



Picture East to West

