

Inspection Photos  
Location Name: State of Colorado 1-16  
API: 05-107-06127



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. Access road overgrown. Noxious weeds (Leafy Spurge) on access road.**

Inspection Photos  
Location Name: State of Colorado 1-16  
API: 05-107-06127



**Photo 3. Noxious weeds (Houndstongue) on location.**



**Photo 4. Noxious weeds (Leafy Spurge) on location.**