

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2018

Submitted Date:

06/05/2018

Document Number:

687902090**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
308324 _____ DURAN, JOHN _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
 Name of Operator: PIONEER NATURAL RESOURCES USA INC
 Address: 5205 N O'CONNOR BLVD STE 200
 City: IRVING State: TX Zip: 75039

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266714	WELL	PR	01/11/2004	GW	071-07830	BOZO 41-22	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			
Type: Compressor	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 266714 Type: WELL API Number: 071-07830 Status: PR Insp. Status: PR

Complaint

Comment: On site at O'Grady house at 8:40am. After introductions I let him know I am headed to Bozo 41-22 to get started. On site at 8:50 am. I take A-scale noise readings. There is a slight wind from the South. There is a muffler on the engine and the exhaust placement direction is to the South. There is a noise baffling shed, over the engine and the open door is to the North. The door is 2/3 open (See Photo). The O'Grady house is about 1/4 mile to the West of wellpad. The well is on the side of a hill in a evergreen, fir and pine forest area. The topography prevented me from taking noise readings at 350 ft. The readings were taken at 255 ft (85 yds). The decibels in parenthesis are the decibels extrapolated to a 350 ft equivalent using the following formula : [db(A)Distance 2 = db(A) Distance 1 - 20 * log 10 (Distance 2/Distance 1)]. TIME : 8:58 am, 9:00, 9:03, 9:05, 9:08, 9:10, 9:12, 9:15 ; WIND (S) : 1.5 mph, 0.7, 1.7, 2.8, 2.8, 2.7, 2.4, 2.9 ; NOISE (A) : 48.9 (46.1), 44.5 (41.7), 49.5 (46.7), 49.8 (47.0), 50.3 (47.5), 49.8 (47.0), 49.9 (47.1), 50.9 (48.1). In compliance with COGCC regulations. Off site at 9:30 am.

On site at O'Grady house at 9:35 am for C-scale noise readings. The readings were taken 25 ft East of the East wall of the O'Grady house. The wind was from the South/SouthEast. TIME : 9:50 am, 9:52, 9:55, 9:58, 10:00, 10:02, 10:05, 10:07 ; WIND (S/SE) : 4.1 mph, 3.5, 2.9, 3.8, 2.9, 3.7, 3.9, 3.1 ; NOISE (C) : 60.0 dbs, 55.1, 53.0, 57.7, 56.4, 57.4, 55.9, 54.5 . In compliance with COGCC regulations. During the test the engine from the Bozo 41-22 and crickets were audible to my ear. I go over the results of A-scale and C-scale readings with Mr. O'Grady. I leave O'Grady house at 12:07 pm.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: 30' x 70'

Corrective Action

Date: _____

Monitoring:	Monitoring Type	Comment`
	Chain	Yellow

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902093	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485331
687902098	Noise baffling shed : 2/3 Open	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485332