

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2018

Submitted Date:

05/30/2018

Document Number:

689701392**FIELD INSPECTION FORM**

Loc ID 335482	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED <b>Findings:</b> 27 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299170	WELL	PR	01/01/2011	GW	045-17584	SHELL 697-34-14B	PR
299171	WELL	PR	07/19/2010	GW	045-17585	SHELL 697-34-14A	PR
299172	WELL	PR	07/19/2010	GW	045-17586	SHELL 697-34-22A	PR
299173	WELL	PR	07/01/2011	GW	045-17587	SHELL 697-34-22B	PR
299894	WELL	PR	01/18/2011	GW	045-17764	SHELL 697-34-08A	PR
299895	WELL	PR	04/10/2010	GW	045-17765	SHELL 797-03-06A	PR
299896	WELL	PR	05/23/2011	GW	045-17766	SHELL 797-03-06B	PR
299897	WELL	PR	07/01/2011	GW	045-17767	SHELL 697-34-08B	PR
300292	WELL	PR	04/28/2011	GW	045-17878	Shell 797-03-15A	PR
300293	WELL	PR	02/21/2012	GW	045-17879	SHELL 697-34-16A	PR
300303	WELL	PR	07/21/2011	GW	045-17882	Shell 797-03-15B	PR
300304	WELL	PR	06/27/2011	GW	045-17883	Shell 797-03-31A	PR
300305	WELL	PR	06/27/2011	GW	045-17884	Shell 697-34-16B	PR
300306	WELL	PR	04/28/2011	GW	045-17885	Shell 797-03-39B	PR
300307	WELL	PR	07/21/2011	GW	045-17886	Shell 797-03-39A	PR
300308	WELL	PR	04/28/2011	GW	045-17887	Shell 797-03-38	PR
300309	WELL	PR	04/28/2011	GW	045-17888	Shell 797-03-37	PR
300310	WELL	PR	06/27/2011	GW	045-17889	Shell 797-03-31B	PR
300311	WELL	PR	06/27/2011	GW	045-17890	Shell 797-03-23A	PR
300312	WELL	PR	06/27/2011	GW	045-17891	Shell 797-03-23B	PR
374710	WELL	PR	06/27/2011	GW	045-18386	Shell 697-34-24	PR

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497

Corrective Action:

Date:

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused poly pipe running along north west edge of loation from tank battery and running off into field west of location.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/30/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		

Comment:	Cover missing from heat unit on separator. Vent turbine is off of separator unit.		
Corrective Action:	Ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/01/2018

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299170	Type:	WELL	API Number:	045-17584	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299171	Type:	WELL	API Number:	045-17585	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299172	Type:	WELL	API Number:	045-17586	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299173	Type:	WELL	API Number:	045-17587	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299894	Type:	WELL	API Number:	045-17764	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299895	Type:	WELL	API Number:	045-17765	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299896	Type:	WELL	API Number:	045-17766	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299897	Type:	WELL	API Number:	045-17767	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 300292	Type: WELL	API Number: 045-17878	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300293	Type: WELL	API Number: 045-17879	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300303	Type: WELL	API Number: 045-17882	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300304	Type: WELL	API Number: 045-17883	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300305	Type: WELL	API Number: 045-17884	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300306	Type: WELL	API Number: 045-17885	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300307	Type: WELL	API Number: 045-17886	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300308	Type: WELL	API Number: 045-17887	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300309 Type: WELL API Number: 045-17888 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300310 Type: WELL API Number: 045-17889 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300311 Type: WELL API Number: 045-17890 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 300312 Type: WELL API Number: 045-17891 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 374710 Type: WELL API Number: 045-18386 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Erosion rill on south east corner of location from over flow of check dam above location. Erosion rill along access road ditch near south west corner of location. Unused dirt berm on location.						Date: 06/30/2018
Corrective Action: Install or repair required BMPs per Rule 1002.f.						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401656747	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477460</a>
689701400	Inspection 689701392 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477458">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477458</a>