

Final Reclamation and Stormwater Inspection

June 4, 2018

Operator: SUNDANCE ENERGY INC – 10340

Location ID: 318044

Inspection Document #: 674902167

Weld County, CO

NENW Section 32 T2N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SUNDANCE ENERGY INC/2N67W32

Location ID: 318044



Photo 1. Photo taken from the well location, facing West. The adjacent well ROCKY MOUNTAIN FUEL 21-32 has been plug and abandoned and all final reclamation activities have been completed.



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.