

Final Reclamation Inspection

May 31, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-10031

Inspection Document #: 682403662

Weld County, CO

SWSE Section 34 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON FAMILY TRUST C #2
API: 05-123-10031



Photo 1. Photo taken from the battery location, facing North. Riser remains at the battery location and should have been removed by 11/31/2017.

Inspection Photos

Location Name: ANDERSON FAMILY TRUST C #2

API: 05-123-10031



Photo 2. Photo taken from the battery location, facing West. Well has been plugged and abandoned. Operator shall complete final reclamation activities at the battery location per Rule 1004 by 8/31/2018.

Inspection Photos

Location Name: ANDERSON FAMILY TRUST C #2

API: 05-123-10031



Photo 3. Photo taken from the well location access point, facing West. Well location and access road appear to meet final reclamation standards.