

Interim Reclamation and Stormwater Inspection

June 4, 2018

Operator: PDC ENERGY INC - #69175

API: 05-123-23409

Inspection Document #: 682403664

Weld County, CO

NENW Section 35 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 1. Photo taken of the northern battery location, facing East. Operator has made repairs and installed a check dam.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 2. Photo taken from the eastern battery location, facing West. Operator has made repairs to the rill erosion.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 3. Photo taken from the entrance of the battery location, facing West. Operator has installed rip-rap and armored around the culvert.

Inspection Photos
Location Name: JEFFERS #21-35
API: 05-123-23409



Photo 4. Photo taken from a portion of the access road. Cattle guard maintenance has been performed.