

Attachment to Supplemental Form 27
Remediation #:10429



View of pit site looking North



View of pit site looking East

Ward Water Pit Closure

Pit site after seed was drilled
and straw was crimped in soil