

Inspection Photos

API#081-07595

Operator: GRMR

Inspection Number: 674104435

Inspection Date: 5/24/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East. Boulders delineate between Reclaimed & Un-Reclaimed areas.

May 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Castor Gulch API#081-07595



Photo#2:

Overview of Location to West. Boulders delineate between Reclaimed & Un-Reclaimed areas.

May 24, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Castor Gulch API#081-07595



Photo#3:

2013 Aerial image of Location before Reclamation.

*
*

May 24, 2018



Photo#4:

2017 Aerial image of Location. Dotted red line indicates delineation between Reclaimed area & Un-Reclaimed area .



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Castor Gulch API#081-07595



Photo#5:
Noxious Weed Houndstongue on Site.



Photo#6:
Noxious Weed White top on Site.

May 24, 2018



Photo#7:
Noxious Weed Mullein on Site.



Photo#8:
Noxious Weed Thistle on Site.

May 24, 2018