

Final Reclamation Inspection

June 4, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-20899

Inspection Document #: 682403670

Weld County, CO

SWNW Section 36 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GADDIS #12-36
API: 05-123-20899



Photo 1. Photo taken from the battery location, facing South. A gas meter run has been left on location. Operator should have removed the equipment per Rule 1004 by 4/4/2017.



Photo 2. Photo taken from the battery location, facing North. Access road remains. All final reclamation should have been completed by 4/4/2017.

Inspection Photos
Location Name: GADDIS #12-36
API: 05-123-20899



Photo 3. Photo taken from the northern battery location, facing East. See comments under Photo 2.



Photo 4. Photo taken from the northern battery location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: GADDIS #12-36
API: 05-123-20899



Photo 5. Photo taken from the well location, facing East. No germination establishment at the wellhead.