

Inspection Photos

API#077-08454

Operator: Caerus

Inspection Number: 674104458

Inspection Date: 5/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Carpenter API#077-08454



Photo#2:

Dalmatian toadflax plants on South side of gated entry track.

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Carpenter API#077-08454



Photo#3:

Dalmatian toadflax plants along gated entry track and on panel fenced perimeter of Location.



Photo#4:

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Carpenter API#077-08454