

Final Reclamation and Stormwater Inspection

June 4, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 318393

Inspection Document #: 674902168

Weld County, CO

NWNW Section 32 T2N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/2N67W32

Location ID: 318393



Photo 1. Photo taken from the location, facing North. Appears the Operator has performed reclamation activities with perennial grasses establishing on site. There is a fence left on location with adjacent annual weeds including Russian thistle and a List C Colorado Noxious weed species cheatgrass and bindweed.



Photo 2. Photo taken from the well location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC/2N67W32

Location ID: 318393



Photo 3. Photo taken from the location, facing South. See comments from Photo 1.



Photo 4. Photo taken from the location, facing West. See comments from Photo 1. There is a barren area at the location that may benefit from additional seeding.

Inspection Photos
Location Name: EXTRACTION OIL & GAS
INC/2N67W32
Location ID: 318393



Photo 5. Photo taken from the East end of the location. A List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*), is found at low densities.



Photo 6. Photo taken from the North end of the location, facing Northwest. See comments from Photo 1.