

Inspection Photos
Location Name: Caerus Location 120803
6/05/2018



Pit and ASTs looking Southwest



West berm of pit showing weed growth and aerator looking south



80K bbl AST within secondary looking west



Condensate ASTs looking southeast

