

Final Reclamation and Stormwater Inspection

June 4, 2018

Operator: SUNDANCE ENERGY INC - 10340

Location ID: 318681

Inspection Document #: 674902165

Weld County, CO

NWSE Section 21 T2N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: SUNDANCE ENERGY INC/2N67W21

Location ID: 318681



Photo 1. Photo taken from the well location showing the existing Leonard 33-21 still on site.



Photo 2. Photo taken from the well location, facing Southwest showing the remaining items on location and the intact access road. See comments under Photo 1.