

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2018

Submitted Date:

06/08/2018

Document Number:

682600498

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10626  
 Name of Operator: DOVER ATWOOD CORPORATION  
 Address: 1875 HARSH AVENUE SE  
 City: MASSILLON State: OH Zip: 44646

**Findings:**

- 2 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Ramos, Martha		martha.ramos@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438219	GAS COMPRESSOR STATION	AC			-	NELLY COPE COMPRESSOR	EI

**General Comment:**

This is an environmental inspection to document status of compressor station. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photos attached to document site status at the time of inspection.

Compressor equipment remains on location.

**Inspected Facilities**

Facility ID: 438219 Type: GAS API Number: - Status: AC Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600503	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489036</a>