

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2018

Submitted Date:

06/08/2018

Document Number:

689301256**FIELD INSPECTION FORM**

Loc ID 335068	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 21 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																							
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>																																																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Rocky, TEP</td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td>All Inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment	Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																								
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections																																																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>210475</td><td>WELL</td><td>PR</td><td>04/12/1995</td><td>GW</td><td>045-06231</td><td>CLOUGH 20</td><td>PR</td></tr> <tr><td>284621</td><td>WELL</td><td>PR</td><td>05/08/2006</td><td>GW</td><td>045-12244</td><td>CLOUGH RWF 323-15</td><td>PR</td></tr> <tr><td>284622</td><td>WELL</td><td>PR</td><td>05/08/2006</td><td>GW</td><td>045-12243</td><td>CLOUGH RWF 413-15</td><td>PR</td></tr> <tr><td>284623</td><td>WELL</td><td>PR</td><td>10/20/2008</td><td>GW</td><td>045-12242</td><td>CLOUGH RWF 524-15</td><td>PR</td></tr> <tr><td>284624</td><td>WELL</td><td>PR</td><td>10/19/2008</td><td>GW</td><td>045-12241</td><td>CLOUGH RWF 514-15</td><td>PR</td></tr> <tr><td>284625</td><td>WELL</td><td>PR</td><td>05/08/2006</td><td>GW</td><td>045-12240</td><td>CLOUGH RWF 523-15</td><td>PR</td></tr> <tr><td>284626</td><td>WELL</td><td>PR</td><td>09/21/2006</td><td>GW</td><td>045-12239</td><td>CLOUGH RWF 424-15</td><td>PR</td></tr> <tr><td>284627</td><td>WELL</td><td>PR</td><td>04/02/2007</td><td>GW</td><td>045-12238</td><td>CLOUGH RWF 23-15</td><td>PR</td></tr> <tr><td>284628</td><td>WELL</td><td>PR</td><td>04/02/2007</td><td>GW</td><td>045-12237</td><td>CLOUGH RWF 423-15</td><td>PR</td></tr> <tr><td>284629</td><td>WELL</td><td>PR</td><td>05/08/2006</td><td>GW</td><td>045-12236</td><td>CLOUGH RWF 414-15</td><td>PR</td></tr> <tr><td>284630</td><td>WELL</td><td>PR</td><td>10/20/2008</td><td>GW</td><td>045-12235</td><td>CLOUGH RMV 157-15</td><td>PR</td></tr> <tr><td>284641</td><td>WELL</td><td>PR</td><td>09/30/2008</td><td>GW</td><td>045-12246</td><td>CLOUGH RWF 324-15</td><td>PR</td></tr> <tr><td>284642</td><td>WELL</td><td>PR</td><td>04/02/2007</td><td>GW</td><td>045-12245</td><td>CLOUGH RWF 314-15</td><td>PR</td></tr> <tr><td>294713</td><td>WELL</td><td>PR</td><td>09/30/2008</td><td>GW</td><td>045-15577</td><td>CLOUGH RWF 534-15</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR	284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR	284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR	284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR	284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR	284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR	284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR	284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR	284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR	284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR	284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR	284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR	284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR	294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																				
210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR																																																																																																																				
284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR																																																																																																																				
284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR																																																																																																																				
284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR																																																																																																																				
284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR																																																																																																																				
284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR																																																																																																																				
284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR																																																																																																																				
284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR																																																																																																																				
284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR																																																																																																																				
284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR																																																																																																																				
284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR																																																																																																																				
284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR																																																																																																																				
284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR																																																																																																																				
294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR																																																																																																																				

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210475	WELL	PR	04/12/1995	GW	045-06231	CLOUGH 20	PR
284621	WELL	PR	05/08/2006	GW	045-12244	CLOUGH RWF 323-15	PR
284622	WELL	PR	05/08/2006	GW	045-12243	CLOUGH RWF 413-15	PR
284623	WELL	PR	10/20/2008	GW	045-12242	CLOUGH RWF 524-15	PR
284624	WELL	PR	10/19/2008	GW	045-12241	CLOUGH RWF 514-15	PR
284625	WELL	PR	05/08/2006	GW	045-12240	CLOUGH RWF 523-15	PR
284626	WELL	PR	09/21/2006	GW	045-12239	CLOUGH RWF 424-15	PR
284627	WELL	PR	04/02/2007	GW	045-12238	CLOUGH RWF 23-15	PR
284628	WELL	PR	04/02/2007	GW	045-12237	CLOUGH RWF 423-15	PR
284629	WELL	PR	05/08/2006	GW	045-12236	CLOUGH RWF 414-15	PR
284630	WELL	PR	10/20/2008	GW	045-12235	CLOUGH RMV 157-15	PR
284641	WELL	PR	09/30/2008	GW	045-12246	CLOUGH RWF 324-15	PR
284642	WELL	PR	04/02/2007	GW	045-12245	CLOUGH RWF 314-15	PR
294713	WELL	PR	09/30/2008	GW	045-15577	CLOUGH RWF 534-15	PR

General Comment: Routine Field Inspection

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-970-285-9377

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Hog Panel fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog Panel fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog Panel fencing		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 14		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 8	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 14	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Centralized Battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210475	Type:	WELL	API Number:	045-06231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284621	Type:	WELL	API Number:	045-12244	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284622	Type:	WELL	API Number:	045-12243	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284623	Type:	WELL	API Number:	045-12242	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284624	Type:	WELL	API Number:	045-12241	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284625	Type:	WELL	API Number:	045-12240	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284626	Type:	WELL	API Number:	045-12239	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	284627	Type:	WELL	API Number:	045-12238	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	284628	Type:	WELL
API Number:	045-12237	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	284629	Type:	WELL
API Number:	045-12236	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	284630	Type:	WELL
API Number:	045-12235	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	284641	Type:	WELL
API Number:	045-12246	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	284642	Type:	WELL
API Number:	045-12245	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	294713	Type:	WELL
API Number:	045-15577	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Retention Ponds						
Berms						
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301257	Inspection Photo 689301257	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489375