

Inspection Photos
Location Name: OM C10 696
Facility ID: 449190
REM #: 10240



Southern portion of OM C10 696 land farm treatment cell.



Pit ID #450300 adjacent to southern portion of land farm.

Inspection Photos
Location Name: OM C10 696
Facility ID: 449190
REM #: 10240



Extent of rock removal from land farmed material.



Northeast portion of land farm where rocks have been screened out.