

# Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: SUNDANCE ENERGY INC - 10340

Location ID: 336511

Inspection Document #: 674902185

Weld County, CO

NENE Section 26 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: SUNDANCE ENERGY INC - 10340 /2N68W26

Location ID: 336511



**Photo 1.** Photo taken looking into the location facing North. Well Location was not constructed at the proposed location based on field observations.