

Inspection Photo
HMU 6-12D
API # 045-21939
Inspection # 689301268



Location Photo #1



Location Photo #2

Inspection Photo
HMU 6-12D
API # 045-21939
Inspection # 689301268



**Location Photo #1, stained rock in tank
battery containment.**