

Inspection Photos

API#077-08260

Operator: Black Hills Plateau Production

Inspection Number: 674104469

Inspection Date: 5/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Walck API#077-08260



Photo#2:
Curley Dock (*Rumex crispus* L.) plants on East slope of Location.

May 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Black Hills PA Walck API#077-08260



Photo#3:
Thistle and Houndstongue plants were still noted scattered across site.



Photo#4

May 31, 2018



Photo#5:
There are several areas of sparse vegetation across site.



Photo#6

May 31, 2018



Photo#7:
There are several areas of sparse vegetation across site.



Photo#8:

May 31, 2018