

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401617127  
Date Received:  
04/23/2018

FIR RESOLUTION FORM

CA Summary:  
4 of 4 CAs from the FIR responded to on this Form  
4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ray, Mandi	505-324-5122	mray@hilcorp.com
Hughes, Jim		jimo.hughes@state.co.us
Leonard, Mike		mike.leonard@state.co.us
Shorty, Priscilla		pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304573  
Inspection Date: 03/29/2018 FIR Submit Date: 04/03/2018 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326093

Location Name: CARTER UTE-N32N10W Number: 13NENE County: LA PLATA  
Qtrqtr: NENE Sec: 13 Twp: 32N Range: 10W Meridian: N  
Latitude: 37.020870 Longitude: -107.880240

FACILITY - API Number: 05-067-00 Facility ID: 215854

Facility Name: CARTER UTE Number: 107  
Qtrqtr: NENE Sec: 13 Twp: 32N Range: 10W Meridian: N  
Latitude: 37.020870 Longitude: -107.880240

CORRECTIVE ACTIONS:

1  CA# 115501

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 04/06/2018

Response: CA COMPLETED Date of Completion: 04/16/2018

Impacted soil removed and gravel from S and SW side of compressor unit

Operator  
Comment:

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

**2**  CA# 115502

Corrective Action: Clean up and remediate impacted soil and gravel to comply with Rule 906.a.

Date: 05/04/2018

Response: CA COMPLETED

Date of Completion: 04/16/2018

Operator Comment: Remediated the contaminated soil on NW side of pump jack and along E side of concrete base

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

**3**  CA# 115503

Corrective Action: Clean up and remove Debris to comply with Rule 603.f.

Date: 05/04/2018

Response: CA COMPLETED

Date of Completion: 04/16/2018

Operator Comment: All trash debris has been picked up and removed from the site

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

**4**  CA# 115504

Corrective Action: Signs need to be replaced or updated to reflect current operator as emergency contact to comply with Rule 210.b.(2).

Date: 05/03/2018

Response: CA COMPLETED

Date of Completion: 04/16/2018

Operator Comment: Sign installed with updated information

COGCC Decision: Approved

COGCC Representative: Follow up inspection completed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Ray

Signed: \_\_\_\_\_

Title: Operation/Regulatory Tech

Date: 4/23/2018 2:24:58 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401617127	FIR RESOLUTION SUBMITTED
401617181	Compressor
401617182	Pumping Unit #1
401617183	Pumping Unit
401617184	Well Sign

Total Attach: 5 Files