

Final Reclamation and Stormwater Inspection

June 7, 2018

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 323290

Inspection Document #: 674902190

Weld County, CO

NWSE Section 23 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323290



Photo 1. Photo taken from the access road looking towards the location, facing Southwest. Appears the Operator has not performed reclamation activities on location. The gravel has not been removed and compaction has not been alleviated.



Photo 2. Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323290



Photo 3. Photo taken from the location. A List B Colorado Noxious weed species, musk thistle (*Carduus nutans*), is found at low densities throughout the site .



Photo 4. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: EXTRACTION OIL & GAS INC /2N68W23

Location ID: 323290



Photo 5. Photo taken from the location. See comments from Photo 1.



Photo 6. Photo taken from the location, facing East. See comments from Photo 1.