

Inspection Photos
Location Name: Lilli Unit #12-6
Location ID: 327025



40.6887, -103.91214, 1459.0m, 157°
Jun 12, 2018 11:18:28 AM



40.68896, -103.91216, 1458.0m, 200°
Jun 12, 2018 11:20:07 AM

Photo 1: Wellhead

Photo 2: Location



Inspection Photos
Location Name: Lilli Unit #12-6
Location ID: 327025



Photo from prior inspection for comparison



Photo 3: Berms repaired

Inspection Photos
Location Name: Lilli Unit #12-6
Location ID: 327025



Photo 4: Weeds in tank battery



Photo 5: Stormwater erosion on NW side of location

Inspection Photos
Location Name: Lilli Unit #12-6
Location ID: 327025



Photo 6: No capacity on water vault sign